













uPVC Ceilings for Everyone





Ceiling Coving Trim II





Internal Corner Trim





Angle Trim







√ldaron Plafon Laminating Films - Wood Available Motifs & Plain Line Variants AD1001A AD1001B AD1002A AD1002B AD1003A AD1003B AD1004A AD1004B AD1005A AD1005B AD1006A AD1006B AD1007A AD1007B AD1008A AD1008B AD1009A AD1009B AD1010A AD1010B AD1011A AD1011B AD1012A AD1012B AD1013A AD1013B AD1014A AD1014B




Disclamer: The colors seen in the brochure may not be 100% the same as the actual product



Disclamer: The colors seen in the brochure may not be 100% the same as the actual product





The Adaron uPVC Ceiling is the latest product from Impack Pratama Group, made from uPVC material that has many advantages over other ceiling materials, including chemical resistance, water resistance, fire retardancy, and durability.

With lightweight, strong its material and interlocking system, the Adaron uPVC Ceiling is easy to apply and adjust as desired. Featuring a variety of attractive designs, the Adaron uPVC Ceiling is a modern solution for ceilings that is available today. The ceiling can be applied according to your preferences, making your room clean, modern, stylish, beautiful, luxurious, and elegant with the Adaron uPVC Ceiling.





Technical Data

Thickness	8 mm
Effective Width	200 mm
Weight	520 gr/m¹
Length	4,5,6 m
Application	Tongue & Groove
Quantity	15 Sheets /box

*The data above is typical data



Applications

Adaron uses a tongue and groove locking system, making it ideal for application in:

- ♦ Living Rooms
- ♦ Bedrooms
- Offices
- ♦ Terraces
- Hospital Rooms

Manufactured by / Diproduksi oleh :





PT. Unipack Plasindo

a subsidiary of **PT Impack Pratama Industri Tbk** Excellence through Passion



Product Handling

- It is recommended that the product be installed at the same temperature as the surrounding room where it will be installed.
- The product should be stored on a flat surface and conditioned for 24 hours to reach the room temperature of the installation area before installation.
- Storing the product on an uneven surface can cause the ceiling to become distorted before installation.

Distributed By / Didistribusikan Oleh: